L Number	Hits	I C C C C C C C C C C C C C C C C C C C	DB	Time stamp
1	0	0 10	USPAT	2003/01/23 14:22
	Ť	thickness" and "gate insulator thickness"		
2	0	349/38-39.ccls. and "thickness of the	USPAT	2003/01/23 14:23
		passivation layer"		
3	6	349/38-39.ccls. and "passivation layer"	USPAT	2003/01/23 14:38
		and "gate insulator"		
4	3	1 2 1 2 7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	USPAT	2003/01/23 14:39
		capacitance" and "aperture ratio" and		
		"image quality"		
5	0	349/38-39.ccls. and "increased auxiliary	USPAT	2003/01/23 14:39
		capacitance"		
6	0	i	USPAT	2003/01/23 14:40
		capacitance"		
7	0	ore, or or comment and source damped and	USPAT	2003/01/23 14:40
Ì		capacitance"	]	
8	34		USPAT	2003/01/23 14:41
		capacitance"	1	
9	6	1	USPAT	2003/01/23 14:45
		and "image quality" and "aperture ratio"		<u> </u>
10	48	( , ,	USPAT	2003/01/23 14:49
		and "aperture ratio"		
11	20	349/38-39.ccls. and "auxiliary	USPAT	2003/01/23 14:56
		capacitance" and "aperture ratio"		
12	22	349/38-39.ccls. and "auxiliary capacitor"	USPAT	2003/01/23 15:23
		and "aperture ratio"		
13	42	· · · · · · · · · · · · · · · · · · ·	USPAT	2003/01/23 15:28
		and "aperture ratio"		
14	35	,	USPAT	2003/01/23 15:55
1		and "aperture ratio" and thickness		
15	1	1 <b>-</b>	USPAT	2003/01/23 15:29
16	384	1,	USPAT	2003/01/23 15:56
17	145	349/138.ccls. and capacitance	USPAT	2003/01/23 15:56

